

# Release Note for Vigor3912 Series

Firmware Version:	4.4.6.1
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	Vigor3912, Vigor3912S

## New Features

- None.

## Improvement

- Improved: Improve the VPN security.
- Corrected: An issue with WUI pre-authentication errors.

### VPN

- Improved: Enhance the L2TP and L2TP over IPsec performance.
- Improved: Enhance the protection for abnormal L2TP packet parsing.
- Corrected: An issue with the abnormal OpenVPN TCP performance.
- Corrected: An issue where the default VPN Dial-out Server Type for VPN LAN-to-LAN was IPsec IKEv2 instead of PPTP.

### Reboot / Crash / Freeze / High CPU

- Corrected: An issue where the router rebooted under high load due to a missing source port in the connection tracking hash.

### Web UI

- Improved: Improve the Firmware Version Before and After display in VigorACS Maintenance >> Firmware Upgrade >> View Log.
- Corrected: An issue where the IP Object page broke after changing a range address to a subnet address.

### Others

- Improved: Refactor the Virtio-Net driver to improve throughput and VM slow-path network performance.
- Corrected: An issue where the router ignored the Primary DNS server.
- Corrected: An issue where the ping packets with TTL lower than 30 were intermittently dropped.
- Corrected: An issue with failure to display 6 GHz information for AP1070C in Central Management >> AP >> Status.
- Corrected: An issue with failure to obtain the correct time in System Maintenance >> Time and Date >> Browser Time.
- Corrected: An issue where the router was unable to obtain an OAuth2 token with Microsoft 365, while Google worked correctly.
- Corrected: An issue where failure to display the Stable and Mainline firmware correctly in System Maintenance >> Firmware Upgrade.
- Corrected: An issue where NetFlow settings were not applied correctly on Vigor3912S, even though VigorConnect sent the NetFlow profile configuration successfully.

## Known Issue

- None.

## Note

- To comply with NIS2 security requirements, the firmware now applies the following defaults: Telnet is disabled, FTP is disabled, and Enforce HTTPS Access is enabled. If Telnet/ FTP access on LAN1 is unavailable after the upgrade, users are advised to verify the settings under System Maintenance >> LAN Access Control.