

Release Note for Vigor3912 Series

Firmware Version:	4.4.6.2
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	Vigor3912, Vigor3912S

New Features

- Add Cloudflare as a Dynamic DNS service provider.
- Add a firmware update reminder in System Maintenance and Dashboard.
- Add an enable/disable switch for the administrator block page in CSM >> DNS Filter. The switch is disabled by default to reduce CPU utilization.

Improvement

Reboot / Crash / Freeze / High CPU

- Corrected: An issue where recursive decapsulation of WireGuard packets caused a crash.
- Corrected: An uninitialized-pointer issue in TR-069 that could cause the router to reboot repeatedly.
- Corrected: An issue where a malformed response from a customized DDNS server caused the router to reboot.
- Corrected: An issue where accessing TR-069 CLI parameters before interface initialization caused read failures or a reboot.

VPN & Security

- Improved: Upgraded the Suricata engine on Vigor3912S to address CVE vulnerabilities.
- Improved: Extended the validity of self-signed OpenVPN server and client certificates to 10 years.
- Corrected: A pre-authentication CGI security issue.
- Corrected: An issue where a firmware upgrade or configuration import changed a VPN LAN to-LAN profile from IKEv1 to IKEv2.
- Corrected: An issue where WireGuard LAN-to-LAN connections were unstable and peer endpoint information was not displayed.
- Corrected: An issue where MyVigor Force Sync and Activate encountered authorization errors after pre-authentication CGI hardening.

Web UI

- Improved: Moved the Port Knocking Status Table to the Diagnostics menu for easier access.
- Corrected: A display issue on Linux Application >> Basic Settings.
- Corrected: An issue where no warning was displayed when an existing username was reused in a Remote Dial-in User profile.

Others

- Corrected: An issue where Strict Bind in Bind IP to MAC required a router reboot before taking effect.
- Corrected: An SNMP response error (Response PDU Too Big / PDU is empty) caused by an incorrect

counter length.

- Corrected: An issue where firmware upgrades failed due to insufficient memory, and firmware upgrade errors were not handled properly.

Known Issue

- None.

Note

- To comply with NIS2 security requirements, the firmware now applies the following defaults: Telnet is disabled, FTP is disabled, and Enforce HTTPS Access is enabled. If Telnet/ FTP access on LAN1 is unavailable after the upgrade, users are advised to verify the settings under System Maintenance >> LAN Access Control.