

Release Note for Vigor2926 Series

Firmware Version:	3.9.9.13
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	Vigor2926, Vigor2926n, Vigor2926ac, Vigor2926L, Vigor2926Vac, Vigor2926Ln, Vigor2926Lac

Vigor2926 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Improved: Enhanced the CGI security (CVE-2024-51139).
- Improved: Enhance the Web GUI Security (CVE-2025-10547).
- Improved: Enhanced the WiFi Driver Security (CVE-2026-20633).
- Improved: Added TR-069 parameters for LTE Specify MCC/MNC.
- Improved: Use HTTPS instead of HTTP for DrayDDNS opcode Update.
- Improved: Strengthened security measures to mitigate buffer overflows, unsanitised input, and uninitialised memory leaks.
- Improved: Updated the text from "Alternative Subject Name" to "Subject Alternative Name" under "VPN and Remote Access > IPsec General Setup."
- Corrected: An issue with SIP account.
- Corrected: An issue with unexpected reboots
- Corrected: An issue that prevented access to the WUI.
- Corrected: An issue with unexpected reboots related to DDNS.
- Corrected: An issue with unexpected reboots caused by IKEv2 attack.
- Corrected: An issue which the daylight saving function did not work.
- Corrected: An issue which the RADIUS Request Interval did not work.
- Corrected: An issue which the VPN Matcher based on OpenVPN did not work.
- Corrected: An issue where the WCF service was unstable and caused slowdowns.
- Corrected: An issue preventing the access list from being applied through the ACS.
- Corrected: An issue that adding dial-in VPN user via ACS3 would reboot the router.
- Corrected: An issue where the WAN1 VLAN Tag options disappeared from the router.
- Corrected: An issue where the router rebooted due to attacks through a URL related to TR-069.

- Corrected: An issue with unexpected self-reboots after configuring the TR-069 ACS on LAN1/VPN.
- Corrected: An issue where an "Authorization Error" appeared when editing a filter rule using Firefox.
- Corrected: An issue which the routers randomly rebooted multiple times a day related to VoIP/SIP.
- Corrected: An issue where the current configuration was not retained after applying a .def file through the ACS.
- Corrected: An issue the dial-out connection restarted when the dial-in device lost its Internet connection.
- Corrected: An issue where the wrong Vigor router model was displayed after upgrading the router firmware.
- Corrected: An issue where the latest firmware download from the WebUI redirected to the non-bonding firmware.
- Corrected: An issue with unexpected system reboots that might have been caused by memory leaks and double-free errors.
- Corrected: An issue that caused firmware upgrades via VigorACS to fail was resolved by initializing the OpenVPN state and index in the SCB reset function.

Known Issue

- None.

Notes

- Vigor router supports the mesh network; however, it is not guaranteed to fit your environment. It might not be available and restricted due to the physical connection, actual environment, signal strength, and excessive interference.
- Remove the simplified APM mechanism, and restore it to full version.