Release Note for Vigor167

Firmware Version:	5.2.8
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	Vigor167

New Features

- None.

Improvement

- Improved: Add TR-069 parameter for the line uptime.
- Improved: Support to query DSL "Line Uptime" via CLI.
- Corrected: An issue with the failure to access the router when the DMZ Host was enabled.
- Corrected: An issue with the failure to set different values for DHCP gateway IP and LAN IP.
- Corrected: An issue with the failure to set TR-069 settings and admin password change via CLI.
- Corrected: An issue with the values for Downstream and Upstream SNR Margin were reversed in DSL Status.
- Corrected: An issue when the device was configured in router mode; the device configuration could not be managed by the VigorACS server.

Known Issue

- To enhance security, firmware version 5.2.3 and the later version modified some system default values and implemented RE pattern checks and command injection checks on system parameters, fields, and values. These changes may cause configuration incompatibilities. Customers attempting to upgrade to the new firmware version may encounter issues such as the firmware version not changing after the upgrade or being unable to import previously backed-up configuration files. In such cases, we recommend that customers reset to factory default settings and reconfigure to resolve the issue.

File and Modem Code

- "Vigor167_v5.2.8.zip" provides modem code 5.12.31.0, and 5.12.18.17.