NO:AP1101-2 V.1

Release Note for Vigor180 Series

Firmware Version:	5.4.2
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	Vigor180 / Vigor180V

Vigor180, a XGS-PON router, provides high-bandwidth, low-latency network connections through optical fiber, suitable for home and business high-speed Internet access needs.

New Features

- Support TR-369 function.
- Supports OMCI Auto Config enabled by default.
- Support Full Bridge mode on P4 (10Gb) by default.
- Supports VEIP configuration for the XGS-PON WAN.
- "Allow Login from WAN" is enabled by default under System Maintenance >> Management.

Improvement

- Improved: Moved the Broadcast XGS-PON Status to LAN option to the Monitoring menu.
- Corrected: An issue where VoIP DND(Do not Disturb) did not work.
- Corrected: An issue where LAN IPv6 traffic via the WAN could not connect to the Internet.
- Corrected: An issue where a redundant IPv6 field was displayed under Configuration >> VoIP >> SIP Account.
- Corrected: An issue where the Port Status LED did not light up in the Dashboard even though the WAN connection was active.
- Corrected: An issue where a Phone2 information was incorrectly displayed under Configuration >> VoIP >> SIP Account>>VoIP Phone Status.
- Corrected: An issue where the Customer and/or Service VLAN Priority settings could not be saved under Configuration > WAN > WAN Connections.
- Corrected: An issue where a network connection using virtual WAN settings could not be established after configuration until the router was rebooted.
- Corrected: An issue where a VPN option was incorrectly displayed under Security >> Firewall Filters >> IP Filters >> WAN to LAN when Specify Interface was enabled.

Known Issue

- None.