

Release Note for Vigor167

Firmware Version:	5.2.9
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	Vigor167

New Features

- None.

Improvement

- Improved: Adjusted the character limit to match the limit used by MyVigor.
- Corrected: An issue where 2FA could not be enabled in Router mode.
- Corrected: An issue where the SIP ALG remained active even when disabled.
- Corrected: An issue where establishing the IPv6 WAN connection caused the IPv4 WAN connection to disconnect.
- Corrected: An issue where the CPE disconnected from ACS3 even though the WAN connection remained stable.

Known Issue

- To enhance security, firmware version 5.2.3 and the later version modified some system default values and implemented RE pattern checks and command injection checks on system parameters, fields, and values. These changes may cause configuration incompatibilities. Customers attempting to upgrade to the new firmware version may encounter issues such as the firmware version not changing after the upgrade or being unable to import previously backed-up configuration files. In such cases, we recommend that customers reset to factory default settings and reconfigure to resolve the issue.

File and Modem Code

- "Vigor167_v5.2.9.zip" provides modem code 5.12.31.0, and 5.12.18.17.