

Release Note for Vigor2135 Series

Firmware Version:	4.5.2.1
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	Vigor2135 / Vigor2135Vac / Vigor2135FVac Vigor2135ac / Vigor2135ax

Vigor2135 features advanced bandwidth control mechanism such as IP-layer, QoS, NAT Session Limitation, Bandwidth Borrowed, etc., to allow easy, flexible, reliable access control and bandwidth management.

New Features

- None.

Improvement

- Improved: Improve the DHCP WAN stability.
- Corrected: An issue that the router did not send periodic information intermittently.

Known Issue

- Do not downgrade the firmware of Vigor router to 4.2.1, if subnet 3 and 4 are enabled.
- For "ax" series model:
The wireless clients might encounter unexpected trouble (e.g., unable to use the printer on LAN) while accessing into Internet if the hardware acceleration is enabled.
To skip hardware acceleration for certain devices, the following telnet command can be used:
`ppa -E -e 1`
`ppa -E -a AA:BB:CC:XX:XX:XX nat/bridge/lipsec`