

Release Note for Vigor2762 Series

Firmware Version:	3.9.9.6
Release Type:	Critical – Upgrade immediately to address urgent security issues or major system risks
Applied Models:	Vigor2762, Vigor2762n, Vigor2762ac, Vigor2762Vac

Vigor2762 series, the high speed router, are perfectly complied with VDSL2 environment including Vigor2762n and Vigor2762ac for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2762 series, you can simultaneously engage these bandwidth-intensive applications, such as high-definition video streaming, online gaming, and Internet telephony / access.

New Features

- None.

Improvement

- Improved: Enhance SQLite 3.9.2 security by applying patches to address multiple known security issues, including CVE-2018-20346, CVE-2018-20505, CVE-2018-20506, CVE-2018-8740, CVE-2019-16168, CVE-2019-19645, CVE-2019-19646, CVE-2019-8457, CVE-2020-11655, CVE-2020-11656, CVE-2020-13434, CVE-2020-13435, CVE-2020-13630, CVE-2020-13631, CVE-2020-13632, CVE-2020-15358, CVE-2022-35737, CVE-2023-7104, CVE-2025-3277, and CVE-2025-6965.
- Corrected: An issue where certain VoIP/SIP attacks could cause the router to reboot unexpectedly.
- Corrected: An issue where the router could reboot unexpectedly under certain VoIP/SIP conditions.

Known Issue

- None.

File and Modem Code

Note: For DSL models, there will be two folders: STD and MDM. The files in MDM folder named folder include different modem codes. If you're using a VDSL line, MDM firmware may brings out better performance.

Available modem codes for Annex A/Annex B are displayed as follows:

- "Vigor2762_v3.9.9.6_STD.zip" provides Annex A modem code 776d07_772801 & 774307_771801, and Annex B modem code 773306_771502 & 773307_771C02.
- "Vigor2762_v3.9.9.6_MDM1.zip" provides Annex A modem code 779517_773F01 & 77B507_775401, and Annex B modem code 779B06_774F02 & 779B07_774C12.
- "Vigor2762_v3.9.9.6_MDM2.zip" provides Annex A modem code 77B506_775401 & 778C06_773F01, and Annex B modem code 779906_774402 & 779B06_774C02.
- "Vigor2762_v3.9.9.6_MDM3.zip" provides Annex A modem code 77C817_775A11 & 77C717_775A11, and Annex B modem code 77C717_775A12 & 779B07_774C12.