

Release Note for Vigor2867 Series

Firmware Version:	5.4.3.1
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	Vigor2867, Vigor2867be

The Vigor2867 Series is a multi-WAN security firewall router that integrates a DSL modem. It is compatible with various DSL protocols, including VDSL2 profile 35b Super Vectoring and ADSL2+, making it suitable for customers seeking high-speed performance.

New Features

- None.

Improvement

- Improved: Enhance security validation for system input handling.
- Improved: Improve transmission performance during 5G wireless and WAN1 throughput testing.
- Improved: Optimize 10G NAT performance to improve upload throughput in high-speed network environments.
- Corrected: An issue where VPN connections could disconnect unexpectedly in certain situations.

Known Issue

- None.

File and Modem Code

- "Vigor2867_v5.4.3.1_STD.zip" provides modem code 5.16.19.0.

Note

- Please ensure that you use the ".rst" firmware file when recovering the router. Note that uploading the ".rst" file will reset the router to factory default settings.
For certain models, a separate ".rst" (reset) firmware file may not be provided. If the ".rst" version is not available, please manually rename the file extension of the ".all" or ".sfw" firmware file to ".rst" to create an equivalent RST firmware file.
Example:
Rename Vigorxxxx_1.2.3.4.sfw → Vigorxxxx_1.2.3.4.rst
Please ensure you back up your configuration before applying a ".rst" firmware, as all settings will be erased during the process.