

## Release Note for Vigor2927 Series

Firmware Version:	4.5.2.1
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	Vigor2927, Vigor2927ac, Vigor2927Vac, Vigor2927L, Vigor2927Lac, Vigor2927ax, Vigor2927F, Vigor2927L-5G, Vigor2927Lax-5G

Vigor2927 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

### New Features

- None.

### Improvement

- Improved: Improve the Web GUI Security.
- Improved: Add a notification that changing the SSL VPN port requires a system reboot.
- Corrected: An issue where the router incorrectly responded TCP port 30022.
- Corrected: An issue that Remote Management TOTP does not work properly.
- Corrected: An issue with the failure to send the Inform after the Global Profile Provision.
- Corrected: An issue with failure to show the Root Device Name in the Mesh Group table in Mesh >> Mesh Setup.
- Corrected: An issue with failure to save the Request IP Address setting in PPP Advanced Settings in VPN and Remote Access>>LAN to LAN.
- Corrected: A display error occurred after configuring the hostname and saving the settings in Firewall >> Edit Filter Set >> Edit Filter Rule.
- Corrected: An issue with failing to enter the PIN code for hotspot authentication when "PIN via Voucher" was selected as the Hotspot Login Method.

### Known Issue

- The EZCast 2 WiFi dongle may not function properly with the Vigor2927ax router. Switching either device to AC mode may resolve the issue.

### Note

- IPsec HMAC (MD5) is no longer supported.