

Release Note for Vigor2960

Firmware Version:	1.5.1.7
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	Vigor2960 Series

Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.9 or later.

New Features

- None.

Improvements

- Improved: Improve Web CGI Security.

Known Issue

- The new firmware version 1.5.1.4 removes the support of the character "%" as the admin password to enhance the WebGUI security. If the character "%" is used as the admin password, please change the password before upgrading to the new firmware version. If the character "%" is used as the admin password and you've upgraded to the new firmware version without changing the password, please use the following CLI commands via Telnet/SSH to change the admin password.
 - enable
 - configure system
 - admin_passwd