

Release Note for VigorAP 920C Series

Firmware Version:	1.4.3
Release Type:	Normal
Applied Models:	VigorAP 920C

New Features

- Add the master AP group ID and group key.
- Add the default DHCP client ID for identifying VigorAP.

Improvement

- Improved: Support AP management using SSH.
- Improved: Improve the OpenSSL security (CVE-2022-0778).
- Improved: Support APP (DrayTek Wireless) config backup/restore function.
- Improved: Support "AutoSelect" for the 2.4GHz channel as the default setting.
- Improved: Add a note to remind the user that the system will reboot after finishing the firmware upgrade.
- Improved: Add a note and a pop-up alert to notify the user not to enable Management VLAN when using the Mesh function.
- Corrected: An issue of WiFi stability.
- Corrected: A display issue of LAN-B information on APM.
- Corrected: An issue of clients communicating with each other with the same radio but different SSIDs.

Known Issue

- System performance will drop when Bonding is enabled.