

Release Note for Vigor1220 Series

Firmware Version:	5.4.3.1
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	Vigor1220, Vigor1220be

Vigor1220 is a XGS-PON VPN router that integrates IP layer QoS, NAT session/bandwidth management, with up to 10Gbps transmission rate to help users work well with large bandwidth. The state-of-the-art routing feature, VPN security and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Improved: Enhance security validation for system input handling.
- Improved: Improve transmission performance during 5G wireless and WAN1 throughput testing.
- Improved: Optimize 10G NAT performance to improve upload throughput in high-speed network environments.
- Corrected: An issue where VPN connections could disconnect unexpectedly in certain situations.

Known Issue

- None.

Note

- Please ensure that you use the ".rst" firmware file when recovering the router. Note that uploading the ".rst" file will reset the router to factory default settings.
For certain models, a separate ".rst" (reset) firmware file may not be provided. If the ".rst" version is not available, please manually rename the file extension of the ".all" or ".sfw" firmware file to ".rst" to create an equivalent RST firmware file.
Example:
Rename Vigorxxxx_1.2.3.4.sfw → Vigorxxxx_1.2.3.4.rst
Please ensure you back up your configuration before applying a ".rst" firmware, as all settings will be erased during the process.