

Release Note for VigorSwitch Q2121x

Firmware Version:	2.9.8
Loader Version:	3.5.1
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	VigorSwitch Q2121x

New Features

- None.

Improvement

- Improved: Improve the web performance based on HTTPS.
- Corrected: An issue with failure to access the CPE information due to TR-069 settings related to VigorACS.
- Corrected: An issue with egress and ingress speeds exceeding 1 Gbps led to inaccuracies in reading the Quality of Service (QoS).

Known Issue

- None.

Note

- After upgrading the firmware with this version, downgrading to the previous version (e.g., V2.7.x) is not allowed if the boot loader was 2.2.0.